

FCB-ER8550/CR8550/ER8530/CR8530

Release Note

Ver.1.01

2018/05/31

Sony Imaging Products & Solutions Inc.

Revision history

| # | Release date | Version | Major revision and comment |
|---|--------------|---------|----------------------------|
| 1 | 2018/04/18 | 1.00 | Initial release |
| 2 | 2018/05/31 | 1.01 | Bug Fix |

CONTENTS

FCB-ER8550/CR8550/ER8530/CR8530..... 0

1. About this Release Version 3

 1.1 General..... 3

 1.2 Software version upgrade method..... 3

2. Additional Function 4

 2.1 Functions added/changed in Ver. 1.01 4

3. Corrected Problems 5

 3.1 Problems corrected in Ver. 1.01..... 5

4. Functional Limitations 6

 4.1 Functional Limitations in Ver. 1.01 6

1. About this Release Version

1.1 General

This release version is 1.01

Target model: FCB-ER8550/CR8550/ER8530/CR8530

1.2 Software version upgrade method

For the version upgrade procedure, refer to the Technical Manual.

2. Additional Function


2.1 Functions added/changed in Ver. 1.01

- None

3. Corrected Problems

3.1 Problems corrected in Ver. 1.01

- Modified the issue that the flare occurs at bottom of a screen with ICR setting, is ON.



Example picture

- Reduce to focus hunting in shooting low light scene.

4. Functional Limitations

4.1 Functional Limitations in Ver. 1.01

- None